




## RISK ASSESSMENT FORM FOR KARIO GLASS PRIVATE LIMITED

CLIENT		RA LEADER	TERENCE ZHU	APPROVED BY:		REFERENCE NUMBER: RA03
PROCESS	Temporary Metal Barrier	RA MEMBER 1	SEKANDAR	SIGNATURE:		ROUTINE / INSTALL GLASS
LOCATION		RA MEMBER 2	ALOM			
ORIGIN DATE		RA MEMBER 3	RANJITH	NAME:	TERENCE ZHU	  <b>Kario Glass Pte Ltd</b> 嘉興玻璃有限公司 408, Tuohi Quarry Road, Singapore 408-0118 Singapore Phone 65008888 T: +65 6742 2888/4338 7239 F: +65 6316 7230 www.kario-glass.com   65774238 Fax 63167230
LAST REVIEW DATE		RA MEMBER 4	RASHED	DESIGNATION:	CEO	
NEXT REVIEW DATE		RA MEMBER 5	ISLAM	DATE:		

HAZARD IDENTIFICATION			RISK EVALUATION				RISK CONTROL					
REF. NO.	WORK ACTIVITY	HAZARD AND POSSIBLE INJURY	EXISTING RISK CONTROL	S SEVERITY	L LIKELIHOOD	RPM RISK MATRIX	ADDITIONAL CONTROL	S SEVERITY	L LIKELIHOOD	RPM RISK MATRIX	PERSON I/C	DUE/DATE REMARKS
1	DISMANTLE EXISTING GLASS BY FIRST REMOVING EXISTING SILICONE SEALANT USING CUTTER	SHARP EDGE OF CUTTER LECERATION	NOT OVER EXTENDING CUTTER TO AVOID BREAKING IT	3	2	6	USING 20MM HEIGHT CUTTER TO PREVENT EASY BREAK OFF	3	1	3	RANJITH	ONGOING SAFE WORK PROCEDURE NO.03
2	INSTALL NEW TEMPORARY METAL BARRIER	BODILY CUTS	WEAR PROPER PPE	4	1	4	CAREFUL PLANNING AND SAFETY BRIEFING BEFORE WORK STARTS	4	1	4	RANJITH	ONGOING SAFE WORK PROCEDURE NO.03